



Service Bulletin

Bulletin No.: 20-NA-197


Date: September, 2020

TECHNICAL

Subject: Malfunction Indicator Lamp (MIL) Illuminated - DTC P0087, P0089, P0191, P026C, P026D, P1089, P163A, P163B, P2293, P228A, P228B, P228C, and/or P228D

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Silverado	2017	2018			L5P	
	Silverado 2500HD/ 3500HD	2019	2020			L5D	
	Silverado 4500HD, 5500HD and 6500HD	2019	2020			L5P	
GMC	Sierra	2017	2018			L5P	
	Sierra 2500HD/ 3500HD	2019	2020			L5P	

Involved Region or Country	North America, Middle East, Israel, Palestine
Condition	Some customers may comment that the MIL is illuminated. Some technicians may find one or more of the following DTCs set in the Engine Control Module (ECM): • P0087: Fuel Rail Low Pressure • P0089: Fuel Pressure Regulator 1 Performance • P0191: Fuel Rail Pressure Sensor 1 Performance • P026C: Injection Quantity Too Low • P026D: Injection Quantity Too High • P1089: Fuel Rail Pressure Performance During Deceleration Fuel Cut-Off • P163A: Control Module Fuel Pressure Regulator 1 Control System Circuitry Performance • P163B: Control Module Fuel Pressure Regulator 2 Control System Circuitry Performance • P2293: Fuel Pressure Regulator 2 Performance • P228A: Fuel Pressure Regulator 1 Control - Forced Engine Shutdown • P228B: Fuel Pressure Regulator 2 Control - Forced Engine Shutdown • P228C: Fuel Pressure Regulator 1 Control Performance - Low Pressure • P228D: Fuel Pressure Regulator 1 Control Performance - High Pressure
Cause	This condition may be caused by corrosion or damaged at the fuel pressure sensor electrical connector.




5652222

Inspect the fuel pressure sensor electrical connector for corrosion or damage.

⇒ It may be necessary to use the terminal test kit with dielectric grease on it and apply/drag each terminal a few times.

Correction



5652223

- If you see a suspect terminal, it may be necessary to removal said terminal and inspect for corrosion, damage and/or signs of the dielectric grease starting to turn black.
- If any of the conditions have been found, replace the electrical connector.

Service Procedure

Refer to *Connector Repairs* in SI.

Parts Information

Causal Part	Description	Part Number	Qty
N/A	CONNECTOR, WRG HARN	19367009	1
N/A	ACDelco Dielectric Lubricant*	12377900 (U.S.) 10953529 (Canada)	1
*There is enough material to do additional vehicles. Store the remaining material for future use.			

Warranty Information

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time
5430860	Connector Kit Replacement	Use the Published Labor Operations Time

Version	1
Modified	Released September 23, 2020

