2007 Chevrolet Equinox

Submodel: | Engine Type: | Liters:

Fuel Delivery: | Fuel:

Subject: The Carpet Is Wet In The Front Passenger Area - keywords cowl dash floor instrument IP leak

panel right sealant sealer strut tower water waterleak #PIT4246 - (01/15/2007)



Models: 2007 Chevrolet Equinox

2007 Pontiac Torrent

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern:

Some owners of an Equinox or Torrent may comment about wet carpet in the front passenger area. This will usually happen during a significant rain storm. This concern can be caused by the body sealant between the side body and cowl may be misplaced, allowing water to pass from the top of the right front strut tower into the cabin.

To check for this leak, apply water at the corner of the strut tower (see picture below).



Click to Enlarge

With the passenger side carpet pulled back, look for water to entering from behind the instrument panel on the right side (See picture below).



Click to Enlarge

Recommendation/Instructions:

To repair this concern, apply body sealant at the strut tower to dash panel area.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safely instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION