Body and Accessories 1979 Mal	160 FSM Body Control System 8-325
Body Control Module Diagnostic Information (cont'd)	
Symptom	Procedure
Engine coolant temperature gauge does not operate properly.	If there is an incorrect engine coolant temperature signal, refer to A Powertrain On Board Diagnostic (OBD)
	System Check in Engine Controls for a diagnosis.  If the signal is OK, use the scan tool in order to monitor the BCM to cluster data.
	<ul> <li>If there is an incorrect engine coolant temperature signal, perform an instrument cluster WOW in SPECIAL FUNCTIONS.</li> </ul>
	<ul> <li>If the engine coolant temperature gauge still does not read correctly, and the BCM is transmitting the wrong signal, replace the BCM. Refer to Body Control Module Replacement and BCM Programming/RPO Configuration.</li> </ul>
	<ul> <li>If the engine coolant temperature signal is OK, replace the instrument cluster. Refer to IP Cluster Replacement in Instrument Panel, Gauges and Console.</li> </ul>
Fuel gauge does not operate properly.	Perform an instrument cluster WOW in SPECIAL FUNCTIONS.
	Replace the cluster if the gauge does not sweep full range. Refer to IP Cluster Replacement in Instrument Panel, Gauges and Console.
	3. Use a Scan Tool in order to read the DTC's.
	Refer to <i>DTC P0462 Fuel Level Sensor Circuit Low Voltage</i> and <i>DTC P0463 Fuel Level Sensor Circuit High Voltage</i> or any Loss of Serial Peripheral Interface (SPI) DTCs.

	Refer to DTC P0462 Fuel Level Sensor Circuit Low Voltage and DTC P0463 Fuel Level Sensor Circuit High Voltage or any Loss of Serial Peripheral Interface (SPI) DTCs.
ABS indicator lights continuously with no loss of serial data.	Use the scan tool in order to monitor the electronic brake control module (EBCM).
	If the EBCM is commanding the BCM to turn the ABS indicator on, refer to the <i>A Diagnostic System Check - ABS</i> for diagnosis.
	If the EBCM is commanding the ABS indicator off, use

the scan tool in order to monitor the BCM SPI serial data bus. · Inspect the CKT 849 at the level switch for a short to ground. · Replace the level switch with a known good switch if a short to ground is found in CKT 849. - If the BCM is commanding the ABS indicator on,

replace the BCM. Refer to Body Control Module Replacement and BCM Programming/RPO Configuration. - If the BCM is commanding the ABS indicator off, replace the Instrument Cluster. Refer to IP Cluster Replacement in Instrument Panel, Gauges and Console.