All AutoZone

MyZone Health Report Powered By Innova

ID #: 3468190210135033

Mileage Reported: 70000 VIN: 2CNFLGEC7B6******

ASE cartified Master Technicians have seen	this issue on your type of vehicle and the most
likely solution is: Replace Camshaft Position	n (CMP) Actuator Solenoid
Definition Code P0013 indicates that the Bank 1 Exhaust Camshaft Position	Actuator circuit had a fault lodged or was disconnected for a predetermined

Error Codes Read

period of time.

P0013 Exhaust Camshaft Position Actuator Circuit / Open (Bank 1)

P0010 Intake Camshaft Position Actuator Circuit / Open (Bank 1)

P0011 Intake Camshaft Position Timing - Over-Advanced (Bank 1)

P0013 Exhaust Camshaft Position Actuator Circuit / Open (Bank 1)

P0010 Intake Camshaft Position Actuator Circuit / Open (Bank 1)

P0013 Exhaust Camshaft Position Actuator Circuit / Open (Bank 1)

P0010 Intake Camshaft Position Actuator Circuit / Open (Bank 1)

Suggested Parts

Suggested Maintenance				
☐ 75000 miles - Change Engine Oil and Filter				
☐ 75000 miles - Inspect Accelerator Pedal Position Assembly				
☐ 75000 miles - Inspect Air Filter				
☐ 75000 miles - Inspect Brake Linings and Hoses				
☐ 75000 miles - Inspect Cooling System				
☐ 75000 miles - Inspect For Fluid Leaks				
☐ 75000 miles - Inspect Fuel System				
☐ 75000 miles - Inspect Parking Brake Operation & Tension				
☐ 75000 miles - Inspect SRS System				
☐ 75000 miles - Inspect Steering & Suspension Components				
☐ 75000 miles - Inspect Wiper & Washer System		44.00		
☐ 75000 miles - Lube Chassis, Suspension and Steering Systems			3119.7	
☐ 75000 miles - Rotate Tires, Inspect Tire Wear, & Adjust Tire Pressure	THE BOOK IN	1741 1		