

TUBE FAILURE
30010 DRIVELINE TORQUE TUBE REPLACEMENT

8868 WARR

10535 WARR

1 84160323 F-TUBE

1 23206449 SEAL

PART#: 84160323 COUNT: 1

M TYPE:

CODE:

0.00	LABOR:	0.00	OTHER:	0.00	TOTAL LINE
------	--------	------	--------	------	------------

EST DROVE, NOISE DUPLICATED, ***DW NEEDED FOR LIFTING AND TRUCK ON LIFT USING STETHOSCOPE TO ISOLATE NOISE, FOUND REAR AFT CAUSING NOISE, FOUND INTERNAL BEARING FAILURE IN REAR *** REMOVED AND REPLACED REAR PROP SHAFT. TEST DROVE, AGAIN NO LONGER PRESENT.

WEST HERR MULTI-POINT INSPECTION

8868 ISPT

10535 ISPT

0.00	LABOR:	0.00	OTHER:	0.00	TOTAL LINE
------	--------	------	--------	------	------------

COMPLETED MPI

NY STATE INSPECTION, SAFETY ONLY

10535CNYSI

0.00	LABOR:	10.00	OTHER:	0.00	TOTAL LINE
------	--------	-------	--------	------	------------

COMPLETED NYS INSPECTION, # 01061091

WELCOME ALL SATURN OWNERS.
716-662-9775