

---

**VIN:** 1GNEK13Z74J108946  
**DECODED:** 2004 Chevrolet Tahoe (LS; LT; Z71)  
**Model Year:** 2004  
**Make:** Chevrolet  
**Model:** Tahoe  
**Trim Level:** LS; LT; Z71

---

**C0291 CODE DEFINITION:**

- Lost Communications with BCM

POSSIBLE CAUSES: None

**TOP REPORTED FIX:**

- Replaced Instrument Cluster w/P1626, U1000, U1016...

**FREQUENTLY REPORTED FIX:**

- Replaced Antilock Brake System (ABS) Control Module w/U1000, U1016, U1026...

**6 OTHER REPORTED FIXES:**

- Repaired Battery To Frame Ground
- Repaired Ground G100 w/B2550, C0237, C0306...
- Repaired Ground G103 w/B2550, C0237, C0306...
- Replaced Fuse(s) w/B1440, B2615, B2948...
- Replaced Turn Signal/Hazard Flasher Module w/B2550, C0237, C0306...
- Tightened Ground G100

**Disclaimer:**

The Possible Causes outlined above may or may not be the cause of your vehicle trouble code(s) being triggered. The Reported Fixes listed are suggestions only, and a fix is not guaranteed by performing any of the above potential solutions. The trouble code summary data may help you pinpoint the type of repair facility that should be consulted. It is strongly recommended that you consult with a knowledgeable professional repair facility for proper diagnosis and repair of trouble code issues. This information is provided without warranty and is subject to the Terms of Use posted at [www.lemurmonitors.com/eula.html](http://www.lemurmonitors.com/eula.html). Reproduction of this information or any portion thereof constitutes infringement of copyright.