
VIN: 1GNEK13Z74J108946

DECODED: 2004 Chevrolet Tahoe (LS; LT; Z71)

Model Year: 2004

Make: Chevrolet

Model: Tahoe

Trim Level: LS; LT; Z71

P1626 CODE DEFINITION:

- Theft Deterrent Fuel Enable Signal Lost

3 POSSIBLE CAUSES:

- Check the serial data circuit for poor connections at the PCM
- Perform the Diagnostic System Check for Powertrain
- Perform the Diagnostic System Check for Theft Deterrent

TOP REPORTED FIX:

- Replaced Body Control Module (BCM)

8 FREQUENTLY REPORTED FIXES:

- Performed Vehicle Theft Deterrent (VTD) System Learn Procedure
- Repaired Ground G103
- Repaired Passlock Sensor Wiring
- Replaced Fuel Pump
- Replaced Fuse(s) w/U1016
- Replaced Ignition Switch
- Replaced Instrument Cluster w/C0291, U1000, U1016...
- Replaced TBC Fuse

25 OTHER REPORTED FIXES:

- Cleaned Battery Cable Terminal(s)
- Cleaned Body Control Module (BCM) Connector

Disclaimer:

The Possible Causes outlined above may or may not be the cause of your vehicle trouble code(s) being triggered. The Reported Fixes listed are suggestions only, and a fix is not guaranteed by performing any of the above potential solutions. The trouble code summary data may help you pinpoint the type of repair facility that should be consulted. It is strongly recommended that you consult with a knowledgeable professional repair facility for proper diagnosis and repair of trouble code issues. This information is provided without warranty and is subject to the Terms of Use posted at www.lemurmonitors.com/eula.html. Reproduction of this information or any portion thereof constitutes infringement of copyright.

VIN: 1GNEK13Z74J108946
DECODED: 2004 Chevrolet Tahoe (LS; LT; Z71)
Model Year: 2004
Make: Chevrolet
Model: Tahoe
Trim Level: LS; LT; Z71

25 OTHER REPORTED FIXES: (Continued)

- Performed Battery Disconnect/Reconnect
- Removed Add-On Alarm System
- Removed Add-On Remote Start System
- Repaired Body Control Module (BCM) Connector w/B1480, B2580
- Repaired Class 2 Serial Data Wiring w/U1300
- Repaired Electronic Brake Control Module (EBCM) Data Wiring w/U1016, U1041, U106
- Repaired Fuse(s) w/U1064
- Repaired Ground G100 w/B2550, C0237, C0291...
- Repaired Ground G104 w/P0120, P0220, P1516...
- Repaired Instrument Cluster Wiring w/U1300
- Repaired Underhood Fuse Block Wiring
- Replaced Battery w/P0300, P0651, U1041...
- Replaced Engine Ground Strap w/P0300, P1381, U1000...
- Replaced Fuel Filter
- Replaced Fuel Pressure Regulator w/P0300, P0651, U1041...
- Replaced High Voltage (HV) Battery w/P0A7F, P1A00, P1a24...
- Replaced Master Power Window Switch w/U1301
- Replaced Passlock Sensor
- Replaced Sensing Diagnostic Module (SDM) w/U1026, U1041, U1064...
- Replaced Starter
- Replaced Turn Signal/Hazard Flasher Module w/B2550, C0237, C0291...
- Repositioned Engine Ground Strap
- Tightened Battery Cable Terminal(s)

Disclaimer:

The Possible Causes outlined above may or may not be the cause of your vehicle trouble code(s) being triggered. The Reported Fixes listed are suggestions only, and a fix is not guaranteed by performing any of the above potential solutions. The trouble code summary data may help you pinpoint the type of repair facility that should be consulted. It is strongly recommended that you consult with a knowledgeable professional repair facility for proper diagnosis and repair of trouble code issues. This information is provided without warranty and is subject to the Terms of Use posted at www.lemurmonitors.com/eula.html. Reproduction of this information or any portion thereof constitutes infringement of copyright.