

---

**VIN:** 1GNEK13Z74J108946  
**DECODED:** 2004 Chevrolet Tahoe (LS; LT; Z71)  
**Model Year:** 2004  
**Make:** Chevrolet  
**Model:** Tahoe  
**Trim Level:** LS; LT; Z71

---

**U1064 CODE DEFINITION:**

- (null)

POSSIBLE CAUSES: None

**4 FREQUENTLY REPORTED FIXES:**

- Replaced Battery
- Replaced Body Control Module (BCM) w/P1626
- Replaced Driver's Door Module (DDM) w/U1000, U1016, U1161
- Replaced Instrument Cluster w/U1016, U1041, U1088

**11 OTHER REPORTED FIXES:**

- Radio w/U1000, U1016, U1161
- Repaired Electronic Brake Control Module (EBCM) Data Wiring w/P1626, U1016, U104
- Repaired Fuse(s) w/P1626
- Repaired Ground G103 w/P0120, P0220, P1516...
- Repaired Ground G104 w/P0120, P0220, P1516...
- Replaced Fuel Pressure Regulator w/P0300, P0651, P1626...
- Replaced Fuse(s) w/B1440, B2615, B2948...
- Replaced High Voltage (HV) Battery w/P0A7F, P1626, P1A00...
- Replaced Ignition Switch w/P0300, P0651, P1626...
- Replaced Powertrain Control Module (PCM) w/U1000, U1016, U1041
- Replaced Sensing Diagnostic Module (SDM) w/P1626, U1026, U1041...

**Disclaimer:**

The Possible Causes outlined above may or may not be the cause of your vehicle trouble code(s) being triggered. The Reported Fixes listed are suggestions only, and a fix is not guaranteed by performing any of the above potential solutions. The trouble code summary data may help you pinpoint the type of repair facility that should be consulted. It is strongly recommended that you consult with a knowledgeable professional repair facility for proper diagnosis and repair of trouble code issues. This information is provided without warranty and is subject to the Terms of Use posted at [www.lemurmonitors.com/eula.html](http://www.lemurmonitors.com/eula.html). Reproduction of this information or any portion thereof constitutes infringement of copyright.