
## 2010 Chevrolet Equinox

Submodel: | Engine Type: | Liters:

Fuel Delivery: | Fuel:



Front Lower Control Arm Bracket Brace Replacement

Callout Component Name

Warning: Refer to Exhaust Service Warning.

Preliminary Procedure

Raise and support the vehicle. Refer to Lifting and Jacking the Vehicle

Front Lower Control Arm Bracket Brace Bolt (Qty: 2)

Caution: Refer to Fastener Caution.

Tighten

30 Y (22 lb ft).

Pront Lower Control Arm Bracket Brace

Top of Page EBSCO Support Site Privacy Policy Terms of Use Copyright

© 2013 EBSCO Industries, Inc. All rights reserved

EBSCO Publishing Green Initiatives

1 of 1 06/05/2015 11:43 AM