

# Manassas Chevrolet

Name \_\_\_\_\_  
 Address \_\_\_\_\_  
 Telephone \_\_\_\_\_  
 Vehicle (VIN) \_\_\_\_\_  
 License \_\_\_\_\_  
 Year: 07  
 Technician \_\_\_\_\_  
 Mileage \_\_\_\_\_  
 Time Printed 4/1/16 8:27 AM

Chevrolet : Tahoe : 2007 : 4X4 : with 20" Wheel

**Front : Left**

Actual	Before	Specified Range	
-0.1°	-0.1°	-0.7°	0.5°
2.8°	2.8°	2.6°	4.6°
0.06°	0.13°	-0.05°	0.15°
11.2°	11.2°	.....	.....
11.1°	11.1°	.....	.....
.....	.....	.....	.....

**Front : Right**

Actual	Before	Specified Range	
0.3°	0.5°*	-0.7°	0.5°
3.1°	3.1°	2.3°	4.3°
0.13°	0.02°	-0.05°	0.15°
10.9°	10.7°	.....	.....
11.2°	11.2°	.....	.....
.....	.....	.....	.....

Camber  
 Caster  
 Toe  
 SAI  
 Included Angle  
 Turning Angle Diff.

**Front**

	Actual	Before	Specified Range	
Cross Camber	-0.4°	-0.6°*	-0.6°	0.6°
Cross Caster	-0.3°*	-0.3°*	-0.2°	0.8°
Cross SAI	0.3°	0.6°	.....	.....
Total Toe	0.18°	0.16°	-0.10°	0.30°
Cross Turn Diff.	.....	.....	.....	.....

**Rear : Left**

Actual	Before	Specified Range	
-0.2°	-0.2°	.....	.....
0.35°	0.36°	.....	.....

**Rear : Right**

Actual	Before	Specified Range	
-0.3°	-0.3°	.....	.....
-0.06°	-0.04°	.....	.....

**Rear**

	Actual	Before	Specified Range	
Cross Camber	0.1°	0.1°	.....	.....
Total Toe	0.30°	0.32°	.....	.....
Thrust Angle	0.20°	0.20°	.....	.....

\* This value is not within specification. Tire wear, handling and safety problems may result.